DMS 1819

A00 **APR**

VEHICLE

SOLVENTS

Toluene

1977

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

REC'D

Required under USDI Safety and Health Regulations for Ship Repairing

Shipbuilding		•	_	1	· · · · · · · · · · · · · · · · · · ·		
		SECT	ION I				
Products Research & Chemical Corporation					EMERGENCY TELEPHON (213) 849-3992	IE NO.	
ADDRESS (Number, Street, City, State, and ZIP) 2919 Empire Avenue, Burbank,	Code! Calif	ornia 9	1505				
CHEMICAL NAME AND SYNONYMS Polysulfide rubber sealing co	mpour	nd			AME AND SYNONYMS 340		
CHEMICAL FAMILY N/A			FORMUL	A N/A			
SECTIO	NII -	HAZAF	RDOUS IN	NGREDI	ENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	*	TLV (Units)	ALL	OYS AND	METALLIC COATINGS	%	TLV (Units)
PIGMENTS	·		BASE ME	TAL	,		
CATALYST Lead Dioxide	5-10	0.2mg/1	13				
VEHICLE	1		METALLI	C COATIN	GS		1

FILLER METAL PLUS COATING OR CORE FLUX OTHERS ADDITIVES OTHERS TLV (Units) HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES

<2 200ppm

SEC	TION III -	PHYSICAL DATA	
BOILING POINT (°F.)	N/A	SPECIFIC GRAVITY (H2O=1)	1.39
VAPOR PRESSURE (mm Hg.) (toluene)	36.7	PERCENT, VOLATILE BY VOLUME (%)	2.0 Max
VAPOR DENSITY (AIR=1) (toluene)	3.14	EVAPORATION RATE	N/A
SOLUBILITY IN WATER	N/A		

SECTION IV - FIRE AND EXP	LOSION HAZARD DATA	•	
FLASH POINT (Method used) 62°F (PMCC)	FLAMMABLE LIMITS UNK	Lel	Uel
EXTINGUISHING MEDIA Foam, CO2, dry chemi			
SPECIAL FIRE FIGHTING PROCEDURES			
	•		-
UNUSUAL FIRE AND EXPLOSION HAZARDS Emission of toxic fu	ımes.		
		•	

SECTION V - HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE 200 ppm, toluene
EFFECTS OF OVEREXPOSURE
Base compound may be irritating to skin.
Accelerator contains a lead compound which may be absorbed through the skin.
EMERGENCY AND FIRST AID PROCEDURES SKIN: Wash thoroughly with soap and water.
EYES: Wash out thoroughly with large amounts of water; call a physician.
INGESTION: Induce vomiting; call a physician.

		SECTION	ON VI - R	EACTIVITY	DATA		
STABILITY	UNSTABLE		CONDITION	MOITIONS TO AVOID			
	STABLE	x					•
Decomposes	(Materials to avoid) when exposed	to oxi	dizing ac	ents.		•	
HAZABDOUS DECC		UCTS					
HAZARDOUS POLYMERIZATION	MAY OCCI			CONDITIONS			
	WILL NOT	OCCUR	Х	•	1		

•					
SECTION VII - SPILL OR LEAK PROCEDURES					
STEPS TO BE TAKEN IN CASE MATERIA Wipe up excess with rags	L IS RELEASED OR SPILL or paper towels:	ED clean area with (chlorinated solvents.		
-	•		,		
		•	•		
waste disposal method Normal trash procedures;	do not incinerate				
<u> </u>					

	SECTION VIII - SPECIAL P	ROTECTION IN	NFORMATION
RESPIRATORY PR	rotection (Specify rype) ed in normal usage.		
VENTILATION	Adequate to minimize solvent vapor.		SPECIAL
,	MECHANICAL (General)		OTHER,
PROTECTIVE GLOVES Recommended.		Not required in normal usage.	
OTHER PROTECT	IVE EQUIPMENT		

SECTION IX - SPECIAL PRECAUTIONS					
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store in closed containers in sheltcred area at ambient temperature.					
OTHER P CAUTIONS Avoid accelerator spillage.					

PAGE (2)

Form OSHA-20 Rev. May 72